

Inspection Photos

Location Name: Golding 4 Tank Facility

Location ID: 335688 & Spill/Release ID: 466858

Inspection Date: August 16, 2019



Photo #1 – Aerial view of the spill/release location.
Spill/release is marked by the black drop (GISOnline Maps).



Photo #2 – Location sign.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Golding 4 Tank Facility

Location ID: 335688 & Spill/Release ID: 466858

Inspection Date: August 16, 2019



Photo #3 – View of the spill/release taken from the pump house looking south.



Photo #4 – View of erosion rills located south of the pump house.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Golding 4 Tank Facility

Location ID: 335688 & Spill/Release ID: 466858

Inspection Date: August 16, 2019



Photo #5 – View of salt staining (red oval) and erosion rills.



Photo #6 – View of the dry stormwater sediment basin.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources