

County: Adams

Township: 1S **Range:** 67W **Section:** 7 **QQ:** NWSW

Original Latitude/ Longitude: 39.977369 / -104.937903

Updated Latitude/ Longitude: 39.972181 / -104.938059

Basis for Location Change:

Location updated to former TB location (aerial imagery circa 1993).

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | |
|---|------------------|
| <input checked="" type="checkbox"/> Form 15 Pit Permit – Doc #: 698409 | Date: 10/06/1978 |
| <input checked="" type="checkbox"/> Field Inspection(s) – Doc #: 698411 | Date: 9/10/1987 |
| Doc #: 698414 | Date: 2/8/1989 |
| Doc #: 1064707 | Date: 6/21/2001 |
| <input type="checkbox"/> Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> COGIS Document – Doc #: | Date: |
| <input type="checkbox"/> Pit Inventory – Doc #: | Date: |
| <input type="checkbox"/> Duplicate Record – Duplicate Pit(s) #: | |
| <input checked="" type="checkbox"/> Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date:

Timing of Pit Closure:

Related wells were plugged and location passed final reclamation inspection 6/21/2001

Pit Status Review Summary:

Based on records review the pit was removed from the location by 1989 inspections. Related wells were plugged and location passed final reclamation inspection 6/21/2001; location is now part of the E-470 right of way. Pit status has been changed to Closed.



