

**Inspection Photos August 14, 2019**  
**Location Name: Walden Land Treatment Facility ID: 427373**



**Location Sign.**



**Gate secured with lock.**



Inspection Photos August 14, 2019  
Location Name: Walden Land Treatment Facility ID: 427373



Trash and debris.



Trash and debris.



**Inspection Photos August 14, 2019**  
**Location Name: Walden Land Treatment Facility ID: 427373**



**Eastern most treatment cell. Darker discolored material had hydrocarbon odor.**



**Eastern most treatment cell. Darker discolored material had hydrocarbon odor.**

**Inspection Photos August 14, 2019**  
**Location Name: Walden Land Treatment Facility ID: 427373**



**Eastern most treatment cell. Darker discolored material had hydrocarbon odor.**



**Eastern most treatment cell. Darker discolored material had hydrocarbon odor.**



**Inspection Photos August 14, 2019**  
**Location Name: Walden Land Treatment Facility ID: 427373**



**Cell adjacent to the eastern most cell.**



**Cell adjacent to the western most cell.**



**Inspection Photos August 14, 2019**  
**Location Name: Walden Land Treatment Facility ID: 427373**



**Pit liner pieces in western most cell.**



**Western most cell.**



**Inspection Photos August 14, 2019**  
**Location Name: Walden Land Treatment Facility ID: 427373**



**Trash in western most cell.**



**Cell adjacent to the eastern most cell.**

**Inspection Photos August 14, 2019**  
**Location Name: Walden Land Treatment Facility ID: 427373**



**Land application area.**



**Land application area.**