

Inspection Photos

Loc#458558

Operator: Sandridge

Inspection Number: 692401275

Inspection Date: 8/15/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Southeast.

July 18, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Marmot Loc#458558



Photo#2:
View along silt fence where BMPs were repaired.



Photo#3:
View along silt fence where BMPs were repaired.

August 14, 2019