

Inspection Photos  
Operator Name: Sandridge Exploration &  
Production LLC  
Location ID: 458558



**6" HDPE Polyflow With tracer wire**



**2 HDPE flowlines exiting bore**



Inspection Photos  
Operator Name: Sandridge Exploration &  
Production LLC  
Location ID: 458558



6" HDPE Polyflow PE 4710



HDPE flowlines test coupons



Inspection Photos  
Operator Name: Sandridge Exploration &  
Production LLC  
Location ID: 458558



Coupling Data



Quality control cut away