

Inspection Photos
Location Name: Kohlhoff USX AB 17-02P
Location ID: 415738




Photo 1 – Pumping Unit, Unused Methanol Tank



Photo 2 – Unused Polish Rod and Fence Panels



Inspection Photos
Location Name: Kohlhoff USX AB 17-02P
Location ID: 415738



Photo 1 – Unused Tubing