


BCU 34-8-198  
API: 05-103-10903  
Inspection: 679705217



**Photo 1. Location.**

BCU 34-8-198  
API: 05-103-10903  
Inspection: 679705217



Photo 2. Well head.



Photo 3. Well head gas leak.

Gas leak



BCU 34-8-198  
API: 05-103-10903  
Inspection: 679705217




Photo 4. Tank label.