

HALLIBURTON

iCem[®] Service

EXTRACTION OIL & GAS-EBUS

Date: Friday, July 05, 2019

Interchange B N35-20-3N Production

Job Date: Monday, May 06, 2019

Sincerely,
Tyler Hill

Legal Notice

Disclaimer:

All information in this report is provided subject to the terms and conditions which govern the services provided by Halliburton. Halliburton personnel use their best efforts in gathering information and their best judgment in interpreting it, but any interpretation, research, analysis or recommendation furnished by Halliburton are opinions based upon inferences from measurements and empirical relationships and assumptions, which inferences and empirical relationships and assumptions are not infallible, and with respect to which professionals in the industry may differ. iCem 3D Displacement results are used to understand how fluids intermix during a cement job. Simulation and 3D displacement results are not intended as and should not be used as a replacement for bond logs in determining top of cement. Current 3D model calculations are known to model more volume than the input volume for standard cases due to known calculation improvements required. For rotational cases, the modeled volume will be impacted by the same calculations impacting the standard cases, as well as additional constraints imposed to make the calculation time required operationally feasible. Therefore, until further notice, 3D displacement results should not be used for replacement of a bond log, or used as an identifier of top of cement. HALLIBURTON IS UNABLE TO GUARANTEE THE ACCURACY OF ANY CHART INTERPRETATION, RESEARCH ANALYSIS, OR JOB RECOMMENDATION and any interpretation or recommendation is not for use of or reliance upon by any third party. The customer has full responsibility for any of its decisions which are based on the information provided in this report.

Table of Contents

1.0	Cementing Job Summary	4
1.1	Executive Summary	4
2.0	Real-Time Job Summary	8
2.1	Job Event Log	8
3.0	Attachments.....	13
3.1	Interchange B N35-20-3N Production.png.....	13

1.0 Cementing Job Summary

1.1 Executive Summary

Halliburton appreciates the opportunity to perform the cementing services on the **Interchange B N35-20-3N** cement **Production** casing job. A pre-job safety meeting was held before the job where details of the job were discussed, potential safety hazards were reviewed, and environmental compliance procedures were outlined.

Approximately 60 bbls of cement were returned to surface.

Halliburton maintains a continuous quality improvement process and appreciates any comments or suggestions that you may have. Halliburton again thanks you for the opportunity to perform service work on this well. We hope to be your solutions provider for future projects.

Respectfully,

Halliburton Ft. Lupton

The Road to Excellence Starts with Safety

Sold To #: 369404		Ship To #: 3954849		Quote #:		Sales Order #: 0905677205	
Customer: EXTRACTION OIL & GAS-EBUS				Customer Rep:			
Well Name: INTERCHANGE B			Well #: N35-20-3N		API/UWI #: 05-014-20843-00		
Field: WATTENBERG		City (SAP): BROOMFIELD		County/Parish: BROOMFIELD		State: COLORADO	
Legal Description: NE SW-10-1S-68W-2483FSL-1585FWL							
Contractor: PATTERSON-UTI ENERGY				Rig/Platform Name/Num: PATTERSON 901			
Job BOM: 7523 7523							
Well Type: HORIZONTAL OIL							
Sales Person: HALAMERICA\HX38199				Srcv Supervisor: Prince Perez			

Job

Formation Depth (MD)		Top	0'	Bottom	18,288'
Job depth MD		18,281'		Job Depth TVD	7,726'
Water Depth				Wk Ht Above Floor	5'

Well Data

Description	New / Used	Size in	ID in	Weight lbm/ft	Thread	Grade	Top MD ft	Bottom MD ft	Top TVD ft	Bottom TVD ft
Casing	0	9.625	8.921	36			0	1652	0	1652
Casing	0	5.5	4.892	17	BTC	P-110	0	18281	0	7726
Open Hole Section			8.75				1652	18288	1652	7726

Tools and Accessories

Type	Size in	Qty	Make	Depth ft	Type	Size in	Qty	Make
Guide Shoe	5.5	1		18,281	Top Plug	5.5	1	
Float Shoe	5.5				Bottom Plug	5.5	1	
Float Collar	5.5	1		18,275	SSR plug set	5.5		
Insert Float	5.5				Plug Container	5.5	1	HES
Stage Tool	5.5				Centralizers	5.5		

Fluid Data

Stage/Plug #: 1

Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
1	Spacer	SBM FDP-C1337-18 CEMENT SPACER SYS	50	bbl	12.5	2.74	16.6	8	1,701

Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal	
2	Cap	ELASTICEM (TM) SYSTEM	585	sack	13.2	1.6	7.75	8	4,534	
3	Lead	ELASTICEM (TM) SYSTEM	615	sack	13.2	1.6	7.7	8	4,736	
4	Tail	ELASTICEM (TM) SYSTEM	1,701	sack	13.2	1.57	7.66	8	13,030	
5	Displacement	MMCR Displacement	20	bbl	8.33			6		
6	Displacement	Displacement	404	bbl	8.33			10		
Cement Left In Pipe		Amount	0 ft		Reason			Wet Shoe		

Mix Water:	pH 7	Mix Water Chloride:	<300 ppm	Mix Water Temperature:	60 °F
Cement Temperature:	## °F	Plug Displaced by:	8.33 lb/gal	Disp. Temperature:	60 °F
Plug Bumped?	Yes	Bump Pressure:	2,414 psi	Floats Held?	Yes
Cement Returns:	60 bbl	Returns Density:	13.2 lb/gal	Returns Temperature:	## °F

Comment

Pumped 50 bbls of FDP Spacer with 20 gallons of D-Air.

Pumped 166.7 bbls of Elasticem.

Pumped 175.3 bbls of Gasstop cement with 1,538 gallons of Latex and 40 gallons of D-air.

Pumped 475.6 bbls of Elasticem.

Pumped 424 bbls of fresh water displacement with MMCR in the first 20 bbls.

Pumped a 5 bbl wet shoe.

3 bbls back on the floats.

2.0 Real-Time Job Summary

2.1 Job Event Log

Type	Seq. No.	Activity	Graph Label	Date	Time	Source	DH Density <i>(ppg)</i>	Comb Pump Rate <i>(bbl/min)</i>	PS Pump Press <i>(psi)</i>	Comments
Event	1	Call Out	Call Out	5/5/2019	19:00:00	USER				CREW CALLED OUT AT 19:00, REQUESTED ON LOCATION 01:00. CREW PICKED UP CEMENT, CHEMICALS, AND PLUG CONTAINER FROM FT. LUPTON, CO. BULK 660, 11023106, 10867439, AND PUMP 11189145.
Event	2	Pre-Convoy Safety Meeting	Pre-Convoy Safety Meeting	5/5/2019	22:45:00	USER				CREW DISCUSSED ROUTES, HAZARDS, AND COMMUNICATION WITH CREW.
Event	3	Crew Leave Shop	Crew Leave Shop	5/5/2019	22:55:00	USER				STARTED JOURNEY MANAGEMENT.
Event	4	Arrive at Location from Service Center	Arrive at Location from Service Center	5/6/2019	00:00:00	USER				END JOURNEY MANAGEMENT. MEET WITH CO. MAN TO DISCUSS JOB; SURFACE CASING- 9/58" 36 LB/FT @ 1,652', 5.5" CASING: 17 LB/FT TOTAL 18,281', 8 1/2" HOLE, TD 18,288', 6' SHOE TRAC, TVD- 7,726'. PUMP FRESH WATER DISPLACEMENT. CASING LANDED @ 04:00 5/6/2019.
Event	5	Safety Meeting - Assessment of Location	Safety Meeting - Assessment of Location	5/6/2019	00:10:00	USER				HAZARD HUNT. DISCUSSED POSSIBLE HAZARDS ASSOCIATED WITH

										LOCATION, RIG UP AND WEATHER.
Event	6	Rig-Up Equipment	Rig-Up Equipment	5/6/2019	00:20:00	USER				RIG UP BULK AND MIXING EQUIPMENT.
Event	7	Pre-Job Safety Meeting	Pre-Job Safety Meeting	5/6/2019	04:40:00	USER	8.28	0.00	-1.00	MEETING WITH HALLIBURTON AND RIG PERSONNEL. COMMUNICATED POTENTIAL SAFETY HAZARDS AND JOB DETAILS.
Event	8	Rig-Up Completed	Rig-Up Completed	5/6/2019	05:35:00	USER	8.28	0.00	-2.00	
Event	9	Start Job	Start Job	5/6/2019	05:39:50	COM4	8.01	0.00	-3.00	BEGIN RECORDING JOB DATA.
Event	10	Drop Bottom Plug	Drop Bottom Plug	5/6/2019	05:40:16	COM4	8.28	0.00	-6.00	PLUG LOADED BY COMPANY MAN.
Event	11	Test Lines	Test Lines	5/6/2019	05:44:27	COM4	8.47	0.00	4861.00	PRESSURE TESTED IRON TO 4,700 PSI. KICKOUTS SET @ 500 PSI, KICKED OUT @ 1,100 PSI, 5TH GEAR STALL OUT @ 2,040 PSI. 4,700 PRESSURE TEST KICKED OUT @ 4,700 PSI
Event	12	Pump Spacer 1	Pump Spacer 1	5/6/2019	05:47:42	COM4	8.35	0.00	4.00	PUMP 50 BBLS OF TUNED PRIME @ 12.5 LB/GAL, 2.74 CUFT/SK, 16.6 GALL/SK. 20 GALS D-AIR. 50 BBLS CALCULATED TO RETURN TO SURFACE. DENSITY VERIFIED BY PRESSURIZED MUD SCALES. PUMP RATE 8 BBLS/MIN @ 570 PSI.
Event	13	Pump Cap Cement	Pump Cap Cement	5/6/2019	05:59:04	COM4	13.06	8.30	846.00	PUMPED 585 SKS OF ELASTICEM @ 13.2 LB/GAL, 1.6 FT3/SK, 7.75 GAL/SK. 166.7 BBLS. HOC CALCULATED @ 2,328.1'. 60 BBLS CALCULATED TO

Event	ID	Description	Material	Date	Time	Code	Vol 1	Vol 2	Vol 3	Notes
										RETURN TO SURFACE. DENSITY VERIFIED BY PRESSURIZED MUD SCALES. PUMP RATE 8 BBLS/MIN @ 860 PSI
Event	14	Pump Lead Cement	Pump Lead Cement	5/6/2019	06:21:56	COM4	13.24	8.00	628.00	PUMPED 615 SKS OF GASSTOP @ 13.2 LB/GAL, 1.6 FT3/SK, 7.7 GAL/SK WITH 40 GALLONS OF D-AIR. 175.3 BBLS. HOL CALCULATED @ 4,295.3', TOL CALCULATED @ 2,328.1'. DENSITY VERIFIED BY PRESSURIZED MUD SCALES. PUMP RATE 8 BBLS/MIN @ 630 PSI
Event	15	Pump Tail Cement	Pump Tail Cement	5/6/2019	06:46:33	COM4	13.35	8.00	759.00	PUMP 1,701 SKS OF ELASTICEM @ 13.2 LB/GAL, 1.57 FT3/SK, 7.66 GAL/SK, 475.6 BBLS. HOT CALCULATED @ 11,657.6', TOT CALCULATED @ 6,623.4'. DENSITY VERIFIED BY PRESSURIZED MUD SCALES. PUMP RATE 8 BBLS/MIN @ 640 PSI.
Event	16	Shutdown	Shutdown	5/6/2019	07:58:11	COM4	8.65	0.00	21.00	SHUTDOWN TO WASH LINES.
Event	17	Drop Top Plug	Drop Top Plug	5/6/2019	08:00:42	COM4	8.05	0.00	-1.00	PLUG LEFT CONTAINER, VERIFIED BY CO. MAN.
Event	18	Pump Displacement	Pump Displacement	5/6/2019	08:00:46	COM4	8.06	0.00	-1.00	BEGIN CALCULATED DISPLACEMENT OF 424 BBLS WITH FRESH WATER. MMCR IN THE FIRST 20 BBLS. PUMP RATE 10 BPM @ 2,750 PSI. CAUGHT CEMENT @ 50 BBLS INTO DISPLACEMENT. SPACER TO SURFACE @ 314 BBLS INTO

										DISPLACEMENT. 50 BBLS OF TUNED SPACER TO SURFACE. CEMENT TO SURFACE @ 364 BBLS INTO DISPLACEMENT. 60 BBLS OF CEMENT TO SURFACE. SLOW RATE TO 3 BPM @ 400 BBLS INTO DISPLACEMENT.
Event	19	Bump Plug	Bump Plug	5/6/2019	09:07:47	COM4	8.14	2.90	2414.00	PLUG BUMPED AT CALCULATED DISPLACEMENT. 2,414 PSI PRESSURED 500 PSI OVER BUMP.
Event	20	Shift Tool - Lower	Shift Tool - Lower	5/6/2019	09:08:19	USER	8.16	0.00	3039.00	SHEARED @ 3,039 PSI FOLLOWED BY A 5 BBL WET SHOE.
Event	21	Check Floats	Check Floats	5/6/2019	09:11:14	USER	8.13	0.00	545.00	RELEASED PRESSURE, FLOATS HELD, 3 BBLS BACK.
Event	22	End Job	End Job	5/6/2019	09:12:28	COM4	8.10	0.00	-9.00	STOP RECORDING JOB DATA.
Event	23	Post-Job Safety Meeting (Pre Rig-Down)	Post-Job Safety Meeting (Pre Rig-Down)	5/6/2019	09:15:00	USER				DISCUSSED POSSIBLE HAZARDS ASSOCIATED WITH WEATHER, LOCATION AND RIGGING DOWN IRON AND HOSES.
Event	24	Rig-Down Equipment	Rig-Down Equipment	5/6/2019	09:25:00	USER				RIG DOWN BULK AND MIXING EQUIPMENT.
Event	25	Rig-Down Completed	Rig-Down Completed	5/6/2019	11:40:00	USER				
Event	26	Pre-Convoy Safety Meeting	Pre-Convoy Safety Meeting	5/6/2019	11:50:00	USER				CREW DISCUSSED ROUTES HAZARDS AND COMMUNICATION WITH CREW.
Event	27	Crew Leave Location	Crew Leave Location	5/6/2019	12:00:00	USER				THANK YOU FOR USING HALLIBURTON – PRINCE PEREZ AND CREW.

3.0 Attachments

3.1 Interchange B N35-20-3N Production.png

