

# *Inspection Photos*

*Loc#324757*

*Operator: Sandridge*

*Inspection Number: 692401279*

*Inspection Date: 8/15/19*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overviews of Location to Northeast.

August 15, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Sandridge Mutual Loc#324757



Photo#2:  
Topsoil soil pile is being stabilized.



Photo#3:  
Weeds have been controlled on Topsoil soil pile.

August 15, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Sandridge Mutual Loc#324757