

Inspection Photos
Location Name: Suckla Farms Inc. E #1
Location ID:317668



Photo 1 WH sign



Photo 2 PU and WH

Inspection Photos
Location Name: Suckla Farms Inc. E #1
Location ID:317668



Photo 3 TNK BTRY WEEDS. NFPA placards missing or peeling off. Crude oil tank volume and identifying labels fading and not legible.



Photo 4 Trash and stained soil.

Inspection Photos
Location Name: Suckla Farms Inc. E #1
Location ID:317668



Photo 5 stained soil under crude oil tank load line



Photo 6 Stained soil under crude oil flow line in TNK BTRY.

Inspection Photos
Location Name: Suckla Farms Inc. E #1
Location ID:317668



Photo 7 valve assembly WEEDS



Photo 8 Sep WEEDS

Inspection Photos
Location Name: Suckla Farms Inc. E #1
Location ID:317668



Photo 9 Meter run WEEDS



Photo 10 Crude oil tank and produced water tank NFPA placards missing or peeling off. Produced water tank has no Identifying label on tank.

Inspection Photos
Location Name: Suckla Farms Inc. E #1
Location ID:317668



Photo 11 TNK BTRY WEEDS



Photo 12 Unused equipment: Unused, unmarked and not LOTO riser behind produced water tank.