

# Final Reclamation Inspection

August 27, 2019

Operator: PDC ENERGY INC - 69175

API: 05-123-21964

Inspection Document #: 697500518

Weld County, CO

NWSW Section 36 T4N R68W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: STATE CORSAIR #13-36  
API: 05-123-21964



**Photo 1.** Photo taken from the wellhead, facing East. Photo illustrates areas around the wellhead have not been properly re-leveled to match the surrounding landscape.

Inspection Photos  
Location Name: STATE CORSAIR #13-36  
API: 05-123-21964



**Photo 2.** Photo taken from the wellhead, facing Southeast. See comments under Photo 1.

Inspection Photos  
Location Name: STATE CORSAIR #13-36  
API: 05-123-21964



**Photo 3.** Reference photo taken southwest of the wellhead, facing South. Photo illustrates that areas around the wellhead have not been properly re-leveled.

Inspection Photos  
Location Name: STATE CORSAIR #13-36  
API: 05-123-21964



**Photo 4.** Photo taken from the tank battery, facing East. It appears recent final reclamation activities were conducted. No equipment was observed at the tank battery or well location.