

Corral Creek 4508  
API: 05-103-08907  
Inspection: 679705229



**Photo 1. Location.**



Corral Creek 4508  
API: 05-103-08907  
Inspection: 679705229



Photo 2. Well head.



Photo 3. Well head valve.

Gas leak



Corral Creek 4508  
API: 05-103-08907  
Inspection: 679705229



Photo 4. Battery sign.