

Inspection Photos
Location Name Neva Dove A #2
API: 05-067-08412



Weeds present within perimeter fencing.



Disturbed area of soil and gravel adjacent to stained/damp area.

Inspection Photos
Location Name Neva Dove A #2
API: 05-067-08412



Location of Spill/Release Point ID #467040.



Stained/damp soil adjacent to well head.