

Inspection Photos

API: 05-017-06433

Operator: Mountain Petroleum

Inspection Date: 8/26/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-06433 | Date: 8/26/2019

Inspection Photos



Photo 1. Facing west along the access road to the location which has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-06433 | Date: 8/26/2019

Inspection Photos



Photo 2. There are two cement pads that remain at the center of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-06433 | Date: 8/26/2019

Inspection Photos



Photo 3. Cement pads are approximately 15 ft. x 4 ft. in size. Unknown depth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-06433 | Date: 8/26/2019

Inspection Photos



Photo 4. Center of the location facing southeast. There is a powerline and meter shed 75' away.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-06433 | Date: 8/26/2019

Inspection Photos



Photo 5. Meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources