

**Inspection Photos**  
**Operator: BP America**  
**Location/API #: 067-06778**  
**Date: 8-21-2019**



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern fill slope from the northeastern corner facing southward.



Photo 3. View of musk thistles within the eastern project area.



Photo 4. View of erosional scouring and cobble run-downs in the eastern project area.



Photo 5. View of reference area vegetation facing southward.