

FAC ID: 117839
Doc# 2615703
Date: 08/09/2019

Pit Status Evaluation Form

Pit Overview:

Pit Name: Ryan 3-26EG	Facility ID: 117839
Current Status: Unknown	Status Date: 01/28/1985
Current Operator: COORS ENERGY COMPANY / 20170	
Updated Operator:	
Form 15 Pit Permit Doc #: 658358	Permit Date: 1/31/1985
Related Facilities:	

County: Weld			
Township: 6N	Range: 65W	Section: 26	QQ: SWNW
Original Latitude/ Longitude: 40.458644 / -104.637458			
Updated Latitude/ Longitude: /			
Basis for Location Change:			
No data to justify change			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|---|-----------------|
| <input type="checkbox"/> | Form 15 Pit Permit – Doc #: 658358 | Date: 1/31/1985 |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 201186 | Date: 6/27/1990 |
| | Doc #: 500167034 | Date: 7/9/1999 |
| | Doc #: | Date: |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> | COGIS Document – Doc #: | Date: |
| <input type="checkbox"/> | Pit Inventory – Doc #: | Date: |
| <input type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: | |
| <input type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 06/27/1990

Timing of Pit Closure:

Pit was closed in 1990 with PA of well

Pit Status Review Summary:

Pit permits indicate that either a bentonite lined earthen pit or a steel tank was used to store produced water. Well was PA and backfill of pit verified by 1990 field inspection.