

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/23/2019

Submitted Date:

08/23/2019

Document Number:

692602429

FIELD INSPECTION FORM

Loc ID 303271 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10112
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

Findings:

- 12 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
252792	WELL	PR	03/25/1982	GW	125-06668	GROSECLOSE 32-30	PR

General Comment:

Routine Inspection

Location			
Lease Road:			
Type	Access		
comment:	Dirt road through farm ground		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease signs mounted to meter shed		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Metal sign by water tank		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Metal fence around unit, wellhead, VGS, water tank and meter shed		
Corrective Action:			Date:
Equipment:			
Type: Pump Jack	# 1		corrective date
Comment:	Churchill unit		
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:	Vertical gas separator 50% buried by meter shed		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	Electric panel, gas scrubber and bellows meter (for domestic use)		
Corrective Action:			Date:

Type: Prime Mover	# 1	
Comment:	Electric motor	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		39.682860,-102.222530
Comment:	Fiberglass open top water tank 50% buried				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	210bbbs
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 252792 Type: WELL API Number: 125-06668 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Fail			

Comment: Access has erosion and needs repaired

Corrective Action: Repair and maintain access

Date: 09/23/2019

Pits: NO SURFACE INDICATION OF PIT