

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/28/2019

Submitted Date:

08/28/2019

Document Number:

692602434**FIELD INSPECTION FORM**
 Loc ID 310921 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10699Name of Operator: OWN RESOURCES OPERATING LLCAddress: 38 PALMER CREST CTCity: SPRING State: TX Zip: 77381**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Jones, Greg	(970) 630-3909	greg.jones@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296614	WELL	PR	11/02/2008	GW	125-11314	KELLER CATTLE 41-10 2S46W	PR

General Comment:Routine Inspection

Location

Lease Road:			
Type	Access		
comment:	Two track through pasture		
Corrective Action:		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by meter shed		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Metal panels around unit, wellhead and meter shed		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Jensen unit		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:	Vertical gas separator 75% buried by wellhead		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric panel		
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	296614	Type:	WELL	API Number:	125-11314	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Casing production								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT