

Inspection Photos
Location Name: Inexco-State 1
Location ID: 312899



Photo 1. Overview of location taken at entrance facing west.



Photo 2. Weeds on and in berm.

Inspection Photos
Location Name: Inexco-State 1
Location ID: 312899



Photo 3. Non-reportable spill – stained soil at wellhead.



Photo 4. Weeds on access road.