

Inspection Photos
Location Name: Mahoney- Perrin #1
Location ID: 317591



Photo #1 Wellhead Sign



Photo #2 Wellhead & Pump jack

Inspection Photos
Location Name: Mahoney- Perrin #1
Location ID: 317591



Photo #3 Wellhead valves appear closed

Photo #4 Control panel appears turned off

Inspection Photos
Location Name: Mahoney- Perrin #1
Location ID: 317591




Photo #5 Stained soil at PJ base

Photo #6 Stained soil around WH

Inspection Photos
Location Name: Mahoney- Perrin #1
Location ID: 317591



Photo #7 Weeds on location