

Inspection Photos
Location Name: UPRR 42 Pan Am AE 5
Location ID: 336263



Photo #1 Wellhead sign faded

Photo #2 PJ

Inspection Photos
Location Name: UPRR 42 Pan Am AE 5
Location ID: 336263



Photo #3 Stained soil at WH

Photo #4 Weeds growing at PJ base

Inspection Photos
Location Name: UPRR 42 Pan Am AE 5
Location ID: 336263



Photo #5 Electrical transformers, breaker panel and meter box