

Inspection Photos
Location Name: Treleaven Tank Battery
Location ID: 435765



Photo 1. Overview of location taken facing north.



Photo 2. Example of equipment stored on location perimeter.



Inspection Photos
Location Name: Treleaven Tank Battery
Location ID: 435765



Photo 3. Example of incomplete tank label and stained soil in battery.



Photo 4. Example of incomplete tank label.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources