

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402161438

Date Received:

08/29/2019

Spill report taken by:

CHESSON, BOB

Spill/Release Point ID:

462451

## SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 906.b. for reporting requirements of spills or releases of E&P Waste or produced fluids. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

### OPERATOR INFORMATION

Name of Operator: <u>VERDAD RESOURCES LLC</u>	Operator No: <u>10651</u>	<b>Phone Numbers</b>
Address: <u>5950 CEDAR SPRINGS ROAD</u>		Phone: <u>(720) 8456901</u>
City: <u>DALLAS</u>	State: <u>TX</u>	Zip: <u>75235</u>
Contact Person: <u>Dean Wagoner</u>		Mobile: <u>( )</u>
		Email: <u>dwagoner@verdadoil.com</u>

### INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 401947666

Initial Report Date: 02/21/2019 Date of Discovery: 02/21/2019 Spill Type: Recent Spill

#### Spill/Release Point Location:

Location of Spill/Release: QTRQTR NWNW SEC 33 TWP 2N RNG 64W MERIDIAN 6

Latitude: 40.101500 Longitude: -104.561710

Municipality (if within municipal boundaries): \_\_\_\_\_ County: WELD

#### Reference Location:

Facility Type: TANK BATTERY

☒ Facility/Location ID No 454345

Spill/Release Point Name: Jackson

☐ No Existing Facility or Location ID No.

Number: 02N-64W-33

☐ Well API No. (Only if the reference facility is well) 05- -

#### Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes

*Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.*

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0

Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0

Estimated Produced Water Spill Volume(bbl): >=100

Estimated Other E&P Waste Spill Volume(bbl): 0

Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: >=100 <=200 inside containment / >=5 <=10 outside containment

#### Land Use:

Current Land Use: CROP LAND

Other(Specify): \_\_\_\_\_

Weather Condition: 20 degrees no wind

Surface Owner: FEE

Other(Specify): Janet & Galen Jackson

#### Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

*As defined in COGCC 100-Series Rules*

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

Between 10:00pm and 3:00am someone entered location and opened the valves on both water tanks halfway. At 3:00am, when Verdad approved personnel arrived, they discovered the leaks and shut the valves. At 4:30am vacuum trucks were called. They sucked up all standing water outside and inside containment. By 7:00am roustabouts were also called to clean up the contaminated soil. The Sheriff's Department was called to report vandalism. Case number has not yet been assigned.

List Agencies and Other Parties Notified:

### OTHER NOTIFICATIONS

Date	Agency/Party	Contact	Phone	Response
2/21/2019	Surface owner	Ms. Jackson	-	Spoke on phone
2/21/2019	Weld county	Jason Maxey	970-4003579	emailed, no response yet

Was there a Grade 1 Gas Leak associated with this E & P waste spill or release? Yes ☐ No ☒

If YES, enter the Document Number of the Initial Grade 1 Gas Leak Report Form 44: \_\_\_\_\_

Was there a reportable accident associated with this E & P waste spill or release? Yes ☐ No ☒

If YES, enter the Document Number of the Initial Accident Report, Form 22: \_\_\_\_\_

### CORRECTIVE ACTIONS

#1	Supplemental Report Date:	08/29/2019
----	---------------------------	------------

Cause of Spill (Check all that apply) ☒ Human Error ☐ Equipment Failure ☐ Historical-Unknown  
☐ Other (specify) \_\_\_\_\_

Describe Incident & Root Cause (include specific equipment and point of failure)

See previous supplemental form. Removed more soil and reanalyzed. Manifest and soil analysis attached.

Describe measures taken to prevent the problem(s) from reoccurring:

See previous supplemental form.

Volume of Soil Excavated (cubic yards): 15

Disposition of Excavated Soil (attach documentation) ☒ Offsite Disposal ☐ Onsite Treatment  
☐ Other (specify) \_\_\_\_\_

Volume of Impacted Ground Water Removed (bbls): \_\_\_\_\_

Volume of Impacted Surface Water Removed (bbls): \_\_\_\_\_

### REQUEST FOR CLOSURE

**Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.**

Basis for Closure: ☒ Corrective Actions Completed (documentation attached)

☐ Work proceeding under an approved Form 27

Form 27 Remediation Project No: \_\_\_\_\_

OPERATOR COMMENTS:

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Dean Wagoner

Title: EHS Field Lead Date: 08/29/2019 Email: dwagoner@verdadoil.com

**COA Type**

**Description**

--	--

**Attachment Check List**

**Att Doc Num**

**Name**

402161463	DISPOSAL MANIFEST
402161466	ANALYTICAL RESULTS
402161468	SITE MAP

Total Attach: 3 Files

**General Comments**

**User Group**

**Comment**

**Comment Date**

		Stamp Upon Approval
--	--	------------------------

Total: 0 comment(s)