

Inspection Photos

Location Name: DYER USX A-66N64W /3NWNE

Location #: 310269



Photo #1

Dyer USX A 3-2 (05-123-26157) Wellsite

Shut-In | SI

*SI/TA Orange decommission tag NOT present
from prior insp.*



Photo #2

Dyer USX A 3-2 Wellsite

Temporarily Abandoned | TA

SI/TA Orange decommission tag NOW present

Inspection Photos

Location Name: DYER USX A-66N64W /3NWNE

Location #: 310269



Colorado Oil & Gas Conservation Commission
40.52056, -104.53383, 1437.0m, 305°
10/02/2018 09:54:41

Photo #3

Dyer USX A 3-2 Wellsite

Shut-In | SI

Unused Equipment

from prior insp.



Colorado Oil & Gas Conservation Commission
40.52059, -104.53373, 1438.0m, 280°
08/29/2019 01:47:31 PM

Photo #4

Dyer USX A 3-2 Wellsite

Temporarily Abandoned | TA

Unused Equipment: Removed

Inspection Photos

Location Name: DYER USX A-66N64W /3NWNE

Location #: 310269



Photo #5

Dyer USX A 3-2, 3-1, 3-7, 3-8, 3-17 Battery site

Abandoned

All equipment removed

Reclamation progressing