

Inspection Photos

Loc#448834

Operator: Sandridge

Inspection Number: 692401291

Inspection Date: 8/15/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Northeast.

August 15, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Grizzly Hebron. Loc#448834



Photo#2:
Topsoil stockpile identified.

August 15, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Grizzly Hebron. Loc#448834



Photo#3:
Berms and slopes are vegetated with ruderal weeds.

August 15, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Grizzly Hebron. Loc#448834



Photo#4:
Trash and debris 6/27/19



Photo#5:
Trash and debris cleaned up, 8/15/19.

August 15, 2019