

MARALEX RESOURCES, INC.– 53255
API# 05-045-06218 DRY FORK FEDERAL #1-29
Inspection Date : 8/28/2019



Location overview looking S.



Wellhead with fence and sign - Temporarily Abandoned.

MARALEX RESOURCES, INC.– 53255
API# 05-045-06218 DRY FORK FEDERAL #1-29
Inspection Date : 8/28/2019



Separator overgrown with vegetation.



Partially buried tank with no berms or labels. Overgrown with vegetation

MARALEX RESOURCES, INC.– 53255
API# 05-045-06218 DRY FORK FEDERAL #1-29
Inspection Date : 8/28/2019



Meter housing



Pit with fence. Overgrown with vegetation

MARALEX RESOURCES, INC.– 53255
API# 05-045-06218 DRY FORK FEDERAL #1-29
Inspection Date : 8/28/2019



Open ended flange inside meter housing