

**Inspection Photos**  
**Location Name: DYER - USX A-66N64W /3NENE**  
**Location #: 306402**



**Photo #1**

**Dyer - USX A 3-17 (05-123-24592) Wellsite**

**Shut-In | SI**

**Weeds**

*SI/TA Orange decommission tag NOT present  
from prior insp.*



**Photo #2**

**Dyer - USX A 3-17 Wellsite**

**Temporarily Abandoned | TA**

*SI/TA Orange decommission tag NOW present  
Weeds mitigated*

## Inspection Photos

Location Name: DYER - USX A-66N64W /3NENE

Location #: 306402



### Photo #3

Dyer USX A 3-2, 3-1, 3-7, 3-8, 3-17 Battery site

**Abandoned**

**All equipment removed**

**Reclamation progressing**