

Final Reclamation Inspection

August 27, 2019

Operator: PDC ENERGY INC - 69175

API: 05-123-21682

Inspection Document #: 697500535

Weld County, CO

SENW Section 36 T4N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: GADDIS #22-36
API: 05-123-21682



Photo 1. Photo taken from the wellhead, facing South. Photo illustrates areas around the wellhead are not reflective of reference area vegetative crop levels.

Inspection Photos
Location Name: GADDIS #22-36
API: 05-123-21682



Photo 2. Close up photo taken from the wellhead. See comments under Photo 1.

Inspection Photos
Location Name: GADDIS #22-36
API: 05-123-21682



Photo 3. Reference photo taken southwest of the wellhead, facing South. See comments under Photo 1.

Inspection Photos
Location Name: GADDIS #22-36
API: 05-123-21682



Photo 4. Photo taken from the associated tank battery, facing East. It appears recent final reclamation activities were conducted. No equipment was observed at the tank battery or well location.