

Final Reclamation Inspection

August 27, 2019

Operator: PDC ENERGY INC - 69175

API: 05-123-20900

Inspection Document #: 697500537

Weld County, CO

NENE Section 36 T4N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: GADDIS #41-36
API: 05-123-20900



Photo 1. Photo taken from the wellhead, facing West. Photo illustrates areas around the wellhead and access road are not reflective of reference area vegetative crop levels.

Inspection Photos
Location Name: GADDIS #41-36
API: 05-123-20900



Photo 2. Photo taken along a portion of the access road, facing West. See comments under Photo 1.

Inspection Photos
Location Name: GADDIS #41-36
API: 05-123-20900



Photo 3. Photo taken along a portion of the access road, facing West. See comments under Photo 1.

Inspection Photos
Location Name: GADDIS #41-36
API: 05-123-20900



Photo 4. Photo taken from the associated tank battery, facing South. It appears there is equipment still in use; however, Operator has failed to reclaim areas that were associated with the location. In addition, Operator has failed to control and manage weeds.

Inspection Photos
Location Name: GADDIS #41-36
API: 05-123-20900



Photo 5. Photo taken from the southern tank battery, facing South. See comments under Photo 4.

Inspection Photos
Location Name: GADDIS #41-36
API: 05-123-20900



Photo 6. Photo taken from inside the equipment illustrating active status.