

Final Reclamation Inspection

August 27, 2019

Operator: PDC ENERGY INC - 69175

API: 05-123-20668

Inspection Document #: 697500539

Weld County, CO

NWNE Section 36 T4N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: GADDIS # 31-36
API: 05-123-20668



Photo 1. Photo taken from the wellhead, facing West. Photo illustrates areas around the wellhead are not reflective of reference area vegetative crop levels.

Inspection Photos
Location Name: GADDIS # 31-36
API: 05-123-20668



Photo 2. Photo taken from the wellhead, facing West. Photo illustrates a recent disturbance that appears to be associated with agricultural activities (i.e., irrigation).