

# Final Reclamation Inspection

August 27, 2019

Operator: PDC ENERGY INC - 69175

API: 05-123-20899

Inspection Document #: 697500543

Weld County, CO

SWNW Section 36 T4N R68W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: GADDIS #12-36  
API: 05-123-20899



**Photo 1.** Photo taken from the battery location, facing North. Operator has removed the remaining equipment. Crop field is currently fallow.



**Photo 2.** Photo taken from the battery location, facing East towards the well location.