

Inspection Photos
Location Name: TELNA 24-22
API#: 05-071-07099
INSP. #: 695101295



PHOTO 1: WELLHEAD



PHOTO 2: WELL SIGN

Inspection Photos
Location Name: TELNA 24-22
API#: 05-071-07099
INSP. #: 695101295



PHOTO 3: UNUSED EQUIPEMNT (2" HOSE AND FITTING).
REMOVE UNUSED EQUIPMENT, COMPLY WITH RULE 603.f.
CA DATE 9-29-19