

# Final Reclamation Inspection

August 29, 2019

Operator: BAYSWATER EXPLORATION AND PRODUCTION LLC - #10261

Location ID: 424905

Inspection Document #: 697500547

Weld County, CO

NWNW Section 30 T7N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Bears 4-30  
Location ID: 424905



**Photo 1.** Photo taken from the well location, facing West. Photo illustrates a land use change to housing development. Well location is now within a pasture for livestock.



Inspection Photos  
Location Name: Bears 4-30  
Location ID: 424905



**Photo 2.** Photo taken from the western tank battery location, facing East. Photo illustrates Operator has failed to perform Final Reclamation activities at the tank battery and remove all equipment.