

Final Reclamation Inspection

August 29, 2019

Operator: EXTRACTION OIL & GAS INC - #10459

Location ID: 426717

Inspection Document #: 697500549

Weld County, CO

NENE Section 25 T7N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Walton 8,17-25 Tank Battery
Location ID: 426717



Photo 1. Photo taken from the eastern tank battery, facing West. Photo illustrates the Operator appears to have performed compaction alleviation; however, equipment remains at the location.

Inspection Photos
Location Name: Walton 8,17-25 Tank Battery
Location ID: 426717



Photo 2. Photo taken from the eastern tank battery, facing South. Photo illustrates the Operator appears to have performed compaction alleviation throughout the off-location flowline area.