

Location Name: Coral Production Corp. - Peterson E-1
Inspection Date: 08/28/2019



Photo # 1 - 05-087-07047



Location Name: Coral Production Corp. - Peterson E-1
Inspection Date: 08/28/2019



Photo # 2 - 05-087-07047 – Oil stained soil at wellhead



Location Name: Coral Production Corp. - Peterson E-1
Inspection Date: 08/28/2019



Photo # 3 - 05-087-07047 – Oil stained soil at wellhead



Location Name: Coral Production Corp. - Peterson E-1
Inspection Date: 08/28/2019



Photo # 4 - 05-087-07047 – electric motor

