

Inspection Photos
Location Name: Shoe #1
Location ID: 317489



Photo #1 WH sign



Photo #2 TB sign

Inspection Photos
Location Name: Shoe #1
Location ID: 317489



Photo #3 Weeds overgrown on access road



Photo #4 Weeds overgrown on Wellsite

Inspection Photos
Location Name: Shoe #1
Location ID: 317489



Photo #5 Weeds overgrown around Heated horizontal separator



Photo #6 Weeds overgrown around as meter

Inspection Photos
Location Name: Shoe #1
Location ID: 317489



Photo #7 Well appears to be SI

Photo #8 Well appears to be SI

Inspection Photos
Location Name: Shoe #1
Location ID: 317489




Photo #9 Well appears to be SI



Photo #10 Weeds overgrown around TB