

**Inspection Photos**  
**Location Name: HRS Church 14-17**  
**Location ID: 329979**



**Photo #1 tank battery Sign**



**Photo #2 Well head has no sign**

**Inspection Photos**  
**Location Name: HRS Church 14-17**  
**Location ID: 329979**



**Photo #3 Gas meter, Weeds on loc.**



**Photo #4 Heated horizontal separator, weeds on loc.**

**Inspection Photos**  
**Location Name: HRS Church 14-17**  
**Location ID: 329979**



**Photo #5 TB**



**Photo #6 Stained soil under Crude oil tank valve**



**Inspection Photos**  
**Location Name: HRS Church 14-17**  
**Location ID: 329979**



**Photo #7 Weeds growing around WH**



**Photo #8 Weeds growing on TB loc.**

Inspection Photos  
Location Name: HRS Church 14-17  
Location ID: 329979



Photo #9 Gas meter last calibrated On 04/07/2017