

Inspection Photos
Location Name: Andrews Lanyard Waterflood #23-18
Location ID: 317994



Photo #1 WH sign



Photo #2 WH over grown with weeds

Inspection Photos
Location Name: Andrews Lanyard Waterflood #23-18
Location ID: 317994



Photo #3 Stained soil WH appears to be leaking