

Inspection Photos
Location Name: Hiawatha B-2
Location ID: 313074



Photo 1. Overview of location taken facing west.



Photo 2. Annual weeds on location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Hiawatha B-2
Location ID: 313074



Photo 3. Incomplete tank labels.



Photo 4. Tubing pressure gauge.

