

Inspection Photos
Location Name: Duncan 1-6
Location ID: 313157



Photo 1. Overview of location taken facing west. Annual weeds visible in photo.



Photo 2. Incomplete tank label.