

Inspection Photos

Location Name: ROTHE-65N63W /31NESW

Location #: 305204



Photo #1

Rothe 23-31 (05-123-22642) Wellsite

Temporarily Abandoned | TA

Weeds



Photo #2

Rothe 23-31 Wellsite

Temporarily Abandoned | TA

Access road: Weeds

Inspection Photos

Location Name: ROTHE-65N63W /31NESW

Location #: 305204



Photo #3

Rothe 24-31, 23-31 Battery

Shut-down | Inactive

Weeds