

Inspection Photos

Location Name: ROTHE-65N63W /31NWSW

Location #: 305177



Colorado Oil & Gas Conservation Commission
40.35391, -104.486, 1387.0m, 76°
09/03/2019 01:30:15 PM

Photo #1

Rothe 13-31 (05-123-22601) Wellsite

Shut-In | SI

Weeds



Colorado Oil & Gas Conservation Commission
40.35067, -104.48805, 1383.0m, 71°
09/03/2019 03:06:03 PM

Photo #2

Rothe #1, 13-31, CSW-31 Battery

Shut-down | Inactive