

Inspection Photos
Location Name: Grassy Creek Coal Co 1
Location ID: 316741



Photo 1. Overview of location taken facing west.



Photo 2. Stained soil at wellhead.



Inspection Photos
Location Name: Grassy Creek Coal Co 1
Location ID: 316741



Photo 3. Stained soil at pump jack exhaust.



Photo 4. Close up of photo 3.

