

Inspection Photos
Location Name: McCallum Unit 65
Location ID: 324616



Photo 1. Overview of location taken facing west.



Photo 2. Photo of wellhead inside housing, stained soil at wellhead.