

# Reclamation Inspection

September 4, 2019

Operator: K P KAUFFMAN COMPANY INC - 46290

Location ID: 332971

Inspection Document #: 697500565

Weld County, CO

NWSW Section 21 T2N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: HLADKY-O'GORMAN #3  
Location ID: 332971



**Photo 1.** Photo taken from the entrance of location. Photo illustrates maintenance needed on cattle guard; this current condition is not keeping cattle out of the oil and gas location.



Inspection Photos  
Location Name: HLADKY-O'GORMAN #3  
Location ID: 332971



**Photo 2.** Photo taken from the entrance of the location, facing Southwest. Photo illustrates the perimeter fence is in disrepair; this current condition is not keeping cattle out of the oil and gas location. Surface owner currently has a temporary hotwire around the perimeter fence to keep cattle out of the oil and gas location.



Inspection Photos  
Location Name: HLADKY-O'GORMAN #3  
Location ID: 332971



**Photo 3.** Photo taken from the eastern location, facing South. Photo illustrates unused equipment. Operator will have to coordinate with the surface owner to remove surface owner equipment to perform weed maintenance and fence repairs.



Inspection Photos  
Location Name: HLADKY-O'GORMAN #3  
Location ID: 332971



**Photo 4.** Photo taken from the southeastern location, facing West. Photo illustrates unmanaged weeds.

Inspection Photos  
Location Name: HLADKY-O'GORMAN #3  
Location ID: 332971



**Photo 5.** Photo taken from the southwestern location, facing Southwest. Photo illustrates fence in disrepair; this current condition is not keeping cattle out of the oil and gas location.



Inspection Photos  
Location Name: HLADKY-O'GORMAN #3  
Location ID: 332971



**Photo 6.** Photo taken from the western location, facing North. Photo illustrates unmanaged weeds. Also, fence around the equipment is in disrepair.