

Reclamation Inspection

September 4, 2019

Operator: K P KAUFFMAN COMPANY INC - 46290

Location ID: 311331

Inspection Document #: 697500567

Weld County, CO

NESW Section 21 T2N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: HLADKY-O'GORMAN #4
Location ID: 332971




Photo 1. Photo taken from the eastern location, facing West. Photo illustrates Kochia establishment (darker green vegetation) along the perimeter of the location. Operator shall perform revegetation activities to comply with Rule 1003 standards.



Photo 2. Photo taken from the location, facing West along the access road. Photo illustrates Kochia establishment (darker green vegetation) along the access road. Operator shall perform revegetation activities to comply with Rule 1003 standards.

Inspection Photos
Location Name: HLADKY-O'GORMAN #4
Location ID: 332971




Photo 3. Photo taken from the northern location, facing East. Photo illustrates Prairie dog establishment. Operator shall control Prairie dog establishment to ensure vegetation is not impacted and meets Rule 1003 vegetation standards. Operator shall perform revegetation activities to comply with Rule 1003 standards. Photo also illustrates Kochia establishment (darker green vegetation).

Inspection Photos
Location Name: HLADKY-O'GORMAN #4
Location ID: 332971



Photo 4. Photo taken from the northern location, facing West. Photo illustrates Prairie dog establishment. See comments under Photo 3.