

Inspection Photos
Location Name: Cuykendall-Lauck #2
Location ID: 317921



Photo #1 WH Sign



Photo #2 TB Sign

Inspection Photos
Location Name: Cuykendall-Lauck #2
Location ID: 317921



Photo #3 WH



Photo #4 Stained soil under PJ pulley

Inspection Photos
Location Name: Cuykendall-Lauck #2
Location ID: 317921



Photo #5 Stained soil pile at PJ base

Photo #6 PJ pulley has no cover

Inspection Photos
Location Name: Cuykendall-Lauck #2
Location ID: 317921



Photo #7 Stained soil under front crude oil tank valve

Photo #8 Stained soil under front crude oil tank valve

Inspection Photos
Location Name: Cuykendall-Lauck #2
Location ID: 317921



Photo #9 Weeds growing on access road

Photo #10 Weeds growing on location

Inspection Photos
Location Name: Cuykendall-Lauck #2
Location ID: 317921



Photo #11 Vertical heater treater/ ECD

Photo #12 pig station

Inspection Photos
Location Name: Cuykendall-Lauck #2
Location ID: 317921



Photo #13 TB

Photo #14 Tank has placards but doesn't show capacity