

Inspection Photos  
Location Name: Lazy #15-8  
Location ID: 331680



Photo #1 WH sign



Photo #2 WH appears to be SI and LOTO for repairs

Inspection Photos  
Location Name: Lazy #15-8  
Location ID: 331680



Photo #3 ECD, heated horizontal separators, gas meter

Photo #4 TB sign

Inspection Photos  
Location Name: Lazy #15-8  
Location ID: 331680



Photo #5 TB

Photo #6 ECDs