

Final Reclamation Inspection

September 2, 2019

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

API: 05-123-24097

Inspection Document #: 697500579

Weld County, CO

SWSE Section 11 T6N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: MILLER #34-11
API: 05-123-24097



Photo 1. Photo taken from the well location access road entrance, facing North. Operator has failed to remove the culvert which is affecting irrigation watering.

Inspection Photos
Location Name: MILLER #34-11
API: 05-123-24097



Photo 2. Photo taken from the well location access road entrance, facing West. See comments under Photo 1.

Inspection Photos
Location Name: MILLER #34-11
API: 05-123-24097



Photo 3. Photo taken from the well location access road entrance, facing South. See comments under Photo 1.