

Inspection Photos

API: 05-071-09462

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/30/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09462 | Date: 8/30/2019

Inspection Photos



Photo 1. 2016 aerial image of the access road and location



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09462 | Date: 8/30/2019

Inspection Photos



Photo 2. Facing northwest along the reclaimed access road. Peren



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09462 | Date: 8/30/2019

Inspection Photos



Photo 3. Facing northwest along the reclaimed access road. Perennial vegetation is well established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09462 | Date: 8/30/2019

Inspection Photos



Photo 4. Facing back to the southeast along the reclaimed access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09462 | Date: 8/30/2019

Inspection Photos



Photo 5. There were numerous shrubs beginning to establish. Photo shows native *Cercocarpus montanus*.



Photo 6. There were also native trees beginning to establish. Photo shows *Pinus ponderosa*.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09462 | Date: 8/30/2019

Inspection Photos



Photo 7. Facing west along the reclaimed access road. Perennial vegetation is well established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09462 | Date: 8/30/2019

Inspection Photos



Photo 8. Facing northwest along the reclaimed access road. Rock rip rap was installed in the two drainages.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09462 | Date: 8/30/2019

Inspection Photos



Photo 9. Facing west along the reclaimed access road toward the drainage area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09462 | Date: 8/30/2019

Inspection Photos



Photo 10. Facing west along the reclaimed access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09462 | Date: 8/30/2019

Inspection Photos



Photo 11. Facing back to the southeast along the reclaimed access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09462 | Date: 8/30/2019

Inspection Photos



Photo 12. Facing west along the reclaimed access road. Perennial vegetation is well established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09462 | Date: 8/30/2019

Inspection Photos



Photo 13. Facing west toward the reclaimed location. Well marker is shown by red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09462 | Date: 8/30/2019

Inspection Photos



Photo 14. Facing north toward the top of the reclaimed location.



Inspection Photos



Photo 15. Facing southwest toward the center of the reclaimed location.



Inspection Photos



Photo 16. Facing northwest toward the top of the reclaimed location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09462 | Date: 8/30/2019

Inspection Photos



Photo 17. Facing southwest toward the bottom of the reclaimed location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09462 | Date: 8/30/2019

Inspection Photos



Photo 18. Facing south toward the bottom of the reclaimed location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09462 | Date: 8/30/2019

Inspection Photos



Photo 19. Facing north toward the reclaimed location standing at the bottom of the slope. Perennial vegetation is well established throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09462 | Date: 8/30/2019

Inspection Photos



Photo 20. View of the location from the bottom of the canyon.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09462 | Date: 8/30/2019